

TO BE RESCINDED

4501-45-09

Fees for certification.

The cost of obtaining the certification of an ignition interlock device shall be paid by the manufacturer of the device to the director of highway safety and deposited in the drivers treatment and intervention fund established by section 4511.191 of the Revised Code. Approved testing laboratories may have fees associated with their work in the testing of the device. Those fees are separate from the certification fee described above.

Effective:

R.C. 119.032 review dates: 03/08/2007

Certification

Date

Promulgated Under: 119.03
Statutory Authority: R.C. 4511.83
Rule Amplifies: R.C. 4511.83
Prior Effective Dates: 9/6/88 (Emer.), 7/22/90